




# Shark Cordless Pet Perfect Charging Port Replacement

Replacing the Charging Port on the Shark Cordless Pet Perfect

Written By: Ashley Calkins



## INTRODUCTION

If you are having a problem with your device's charging port, here is a step by step guide to replace a faulty charging port.

---



### TOOLS:


- [Soldering Station](#) (1)
  - [Phillips #2 Screwdriver](#) (1)
-

## Step 1 — Charging Port



- Remove the dust cup container from the motor housing.


## Step 2



- Remove the five 14mm screws with the PH 2 bit. Once all the screws are removed, pull one part of the housing away from the other.





## Step 3



- Pull the charging port mount away from the housing. Once separated, pull the the charging port out of the mount to access the charging port itself.

## Step 4



- Use a soldering iron to disconnect the wires from both terminals.
-  For soldering help, check out iFixit's [How to Solder and Desolder Connections](#) guide.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-07-06 01:45:23 PM.